Agenda - Executive Policy Committee – September 21, 2006

Moved by Councillor

That Rule 9.3 of the Procedure By-law be suspended in order that the following item, which was received too late to be placed on the regular agenda, may also be considered by Committee at this time.

ADDENDUM REPORTS

Item No. 24 Coronation Park Cenotaph Restoration Project - Land Dedication Reserve
File EP-2

COMMUNITY COMMITTEE RECOMMENDATION:

On September 19, 2006, the Riel Community Committee recommended to the Executive Policy Committee:

1. That funding to assist with the cost of the Coronation Park Cenotaph Restoration Project, in the amount of $7,000.00, be allocated from the Riel Land Dedication Reserve to the Norwood Legion.

2. That the Proper Officers of the City be authorized to do all things necessary to implement the intent of the foregoing.

DECISION MAKING HISTORY:

COMMUNITY COMMITTEE RECOMMENDATION:

On September 19, 2006, the Riel Community Committee recommended:

1. That funding to assist with the cost of the Coronation Park Cenotaph Restoration Project, in the amount of $7,000.00, be allocated from the Riel Land Dedication Reserve to the Norwood Legion.

2. That the Proper Officers of the City be authorized to do all things necessary to implement the intent of the foregoing,

and submitted the matter to the Executive Policy Committee.

Veterans Affairs Canada / Anciens Combattants Canada

Canada Remembers Division RECEIVED JUN 2 6 2006 Direction générale du Canada se Souvient

Cenotaph/Monument Restoration Program (CMRP) Application Form

1. Applicant Information *(please print)*

Name of contact: Robert J Dunbar	Organization: Legion
☒ Mr. ☐ Mrs. ☐ Ms. ☐ Other, specify	Preferred language of communication: ☒ English ☐ French
Telephone No. Extension	Facsimile No. ( )

ADDRESS

Street: 166 Thomas Berry Sq	City: Wpg
Province/Territory: MB / Postal Code: R2H-0P7	E-mail address

2. General Cenotaph/Monument Information *(please print)*

Ownership of Cenotaph/Monument *(Municipal/Royal Canadian Legion/Other - specify)*: Federal Government

National Inventory of Military Memorials Registration Number	Official heritage designation of Cenotaph/Monument

LOCATION OF CENOTAPH/MONUMENT

Street address or nearest cross streets: Taché St. at St. Mary's Rd.	City: Winnipeg
Province/Territory: Manitoba	Description of the location *(e.g. in a park, on a street corner, on the side of a building, etc.)*: In Coronation Park

Are you applying for funding for ☒ conservation work ☐ consultation fees to identify required conservation work

Explain what this Cenotaph/Monument commemorates, and describe other reasons for which it is valued. *(For example, the Cenotaph/Monument may also be valued for a unique design, special materials used in its construction, or the importance of its placement within its site or placement.)*

Cenotaph commemorates WWI, WWII, Korea Veterans of Norwood and St Boniface area. WWI era construction.

Is the community supportive of the project, and will community groups support ongoing maintenance once the cenotaph/monument has been repaired?

Norwood Legion is undertaking it's cleaning and is keeping watch over Cenotaph.

Describe the importance of the cenotaph/monument to the community. *(e.g. Is it used for remembrance activities?)*

Ceremony every Remembrance day - New bandshell built recently for celebrations and weekly summer festivities

Overall dimensions of cenotaph/monument *(Include height where possible, and size of base.)*

15 ft. wide x 15 ft. deep x 25 ft high aprox.

3. Environment of the Cenotaph/Monument *(check all that apply)*

The cenotaph/monument is regularly exposed to:

- ☐ Road de-icing salts
- ☐ Ocean/marine salts
- ☐ Road splash
- ☐ Ocean or fresh water spray
- ☒ Overhanging trees
- ☐ Precipitate from nearby heavy industry
- ☒ Vandalism
- ☐ Inappropriate uses *(e.g. skateboarding)*
- ☒ Other, specify Old Age – Weather Worn
- ☐ There are large trees or tree roots near the foundation.
- ☐ Water ponding or poor drainage away from the cenotaph/monument is a recurring problem.
- ☐ Soil movements *(e.g. frost heaving, settlement)* are a known problem.
- ☐ The soil is known to contain sulphates.

Describe any unique or special restrictions around the cenotaph/monument.
(e.g. noise or work restrictions, limited access for construction equipment.)

4. Construction History of the Cenotaph/Monument

Year of construction *(if known)*
1920s

Description of any previous conservation or repairs.
(If known, include type of work completed and when. Also, provide photographs of cenotaph/monument before and after construction work, and copies of any repair/conservation drawings, if available.)

Cenotaph was cleaned and re-lettered about 7-10 years ago. The Top remains Dirty. The Top of the Cenotaph and the rest should be Sealed.

PLEASE PROVIDE COPIES OF ORIGINAL CONSTRUCTION DRAWINGS IF AVAILABLE

5. Foundation of the Cenotaph/Monument *(check all that apply)*

Type

- ☐ None or on a grade
- ☐ Crushed stone
- ☐ Concrete slab on grade
- ☒ Concrete footing and pier
- ☐ Stone footing and pier
- ☐ Unknown
- ☐ Steel, wood or concrete piles
- ☐ Other, specify Not certain - but Solid

Bearing Soil

- ☐ Rock
- ☐ Organic soil *(peat, silts)*
- ☐ Unknown
- ☐ Reasonable free-draining sandy soil
- ☒ Reasonable free-drain coarse granular

Does the foundation extend below the frost line? ☒ Yes ☐ No ☐ Unknown

Is permafrost present in the soil? ☐ Yes ☒ No ☐ Unknown

6. Materials of the Cenotaph/Monument *(check all that apply)*

METAL

Type

☐ Bronze ☐ Copper ☐ Steel ☐ Cast iron ☐ Zinc ☐ Unknown
☐ Brass ☐ Aluminum ☐ Lead ☐ Wrought iron ☐ Other, specify _____

Fabrication

☐ Cast ☐ Stamped ☐ Other, specify _____ ☐ Unknown

Finish

☐ None ☐ Wax ☐ Enamel ☐ Other, specify _____ ☐ Unknown

STONE MASONRY

Type of stone

☐ Granite ☒ Limestone ☐ Marble ☐ Sandstone ☐ Other, specify _____
☐ Unknown

Original quarry Tyndal, MB. ☐ Unknown

Bedding mortar

☐ Lime based mortar ☐ Cement based mortar ☒ Unknown

Pointing

☒ Lime based mortar ☒ Cement based mortar ☐ Synthetic caulk ☐ Putty
☐ Lead ☐ Other, specify _____ ☐ Unknown

Assembly

☐ Single stone ☒ Solid masonry ☐ Concrete core ☒ Unknown
☐ Hollow core ☐ Other, specify _____

Coating

☐ None ☐ Parging ☒ Other, specify Sealed - Silicone 10 yrs ago ☐ Unknown

BRICK MASONRY

Type of brick

☐ Clay ☐ Terra cotta ☐ Concrete ☐ Other, specify _____ ☒ Unknown

Bedding mortar

☐ Lime based mortar ☐ Cement based mortar ☐ Unknown

Pointing

☐ Lime based mortar ☐ Cement based mortar ☐ Putty ☐ Unknown
☐ Other, specify _____

Assembly

☐ Solid masonry ☐ Concrete ore ☐ Hollow core ☐ Unknown
☐ Other, specify _____

Coating

☐ None ☐ Parging ☐ Other, specify _____ ☐ Unknown

7. Defining the Problems *(check all that apply - continued)*

Environment wear

☒ Unintended exposure of foundation

Improper use

☐ Marring of surfaces ☐ Staining of surfaces ☐ Accumulation of inappropriate coatings *(e.g. skateboard wax)*

Other symptoms, specify

Aging - Dirt from old Age - Need Washing.

PROBLEMS AFFECTING MASONRY *(STONE AND BRICK)*

Deterioration of masonry unit

☐ Delamination ☒ Blistering ☐ Sedimentary bedding openings
☒ Pitting ☒ Cracking ☒ Loss of stone piece

Deterioration of mortar

☒ Cracking ☒ Hairline cracks ☒ Open joints

Deterioration of masonry

☐ Bulging ☒ Displacement of masonry unit ☐ Rotation or twisting of masonry unit

Damage to masonry unit

☒ Chipping ☐ Scratching ☒ Loss of unit

Build up of organic growth

☐ Grasses ☐ Lichens ☐ Moss

Staining

☐ Moisture ☐ Iron ☐ Copper ☐ Biological ☐ Moss

Other symptoms, specify

PROBLEMS AFFECTING CONCRETE COMPONENTS

Deterioration

☐ Spalling ☐ Delamination ☐ Cracking
☐ Micro-cracking ☐ Chipping ☐ Corrosion of reinforcement

Deformation of concrete

☐ Cracking ☐ Settlement

Build-up of organic growth

☐ Grasses ☐ Lichens ☐ Moss

Staining

☐ Moisture ☐ Iron ☐ Copper ☐ Biological ☐ Moss

Other symptoms, specify

7. Defining the Problems *(check all that apply - continued)*

PROBLEMS AFFECTING METAL COMPONENTS

Deterioration of metal

☐ Corrosion ☐ Oxidation

Damage

☐ Denting ☐ Cracking ☐ Splitting ☐ Tearing
☐ Deformation ☐ Loss of elements ☐ Failure of attachments

Build up of organic growth

☐ Grasses ☐ Lichens ☐ Moss

Deterioration of surfaces

☐ Biological staining ☐ Loss of finish

Other symptoms, specify

PROBLEMS AFFECTING WOOD COMPONENTS

Biological deterioration

☐ Decay ☐ Insect attack

Mechanical damage

☐ Cracking ☐ Splitting ☐ Deformation
☐ Loss of elements ☐ Abrasion ☐ Chemical damage at metal fasteners

Build-up of organic growth

☐ Moulds ☐ Lichens ☐ Moss

Staining

☐ Moisture ☐ Biological ☐ Copper ☐ Iron

Surface finish

☐ Loss of deterioration

Other symptoms, specify

PLEASE PROVIDE THE FOLLOWING INFORMATION

7.a Decscribe any events or circumstances that caused the problems.

Base made of Tyndall stone is cracked Missing and Broken - 9 pcs need to be replaced and entire base is to be repointed

7. Defining the Problems *(check all that apply - continued)*

7.b Indicate if the problems are recent or if it has been ongoing for several years.
(If ongoing, please specify approximately how long.)

Very gradual degredation - from freeze - thaw

7.c Identify if any professionals or specialists have been involved in the assessment of the problems to be addressed by this submission.
(If so, please include copy of any condition assessment or investigation reports that have been produced.)

8. Proposed Solutions

THIS SECTION EXPLAINS THE APPLICANT'S PLAN TO ADDRESS THE PROBLEMS AFFECTING THEIR CENOTAPH/MONUMENTS.

8.a Describe the scope of the planned conservation work.

We would like to re-plate 9 pcs of Tyndall Stone and re-point all of base - Also Clean the top of the Cenotaph - Apply Sealant to entire Stone

8.b List drawings and specifications attached to this submission for the conservation work to be funded by this program.
(Note that drawings and specifications can range in detail and consent depending on the scope of work: for simple projects this information could be contained on a single drawing with notes, whereas more complex projects may require comprehensive sets of drawings and specifications. Specifications should include all materials to be used for the work.)

To match existing work.

8.c Identify how the planned work addresses the causes of the problem identified in Section 7.

It will be repaired

9. Financing

Budgeted breakdown of the cost of the work, including total project costs
(Please attach copies of all contractors' estimates to this submission.)

EXPENSES	Cost (cash)	Cost (in-kind)*	Total cost
Consulting Fees	$	$	$
Labour	$ 7000.00	$	$ 7000.00
Material	$ 5000.00	$	$ 5000.00
	$	$	$
	$	$	$
TOTAL COST FOR THE PROJECT	$	$	$ 12,000.00

Source of funding *(Please provide names of all contributors. Use another sheet if necessary)*

REVENUE	✓	Cost (cash)	Cost (in-kind)*	Total cost
Organization/Applicant	☐	$	$	$
Other non-profit organizations	☐	$	$	$
Private sector	☐	$	$	$
Fund raising	☐	$	$	$
Other federal government departments	☐	$	$	$
Provincial government	☐	$	$	$
Municipal government	☐	$	$	$
Veterans Affairs Canada	☐	$	$	$
	☐	$	$	$
TOTAL REVENUES		$	$	$

* - Only 25% of the overall budget can be contributions made by in-kind donations.

✓ - Revenue source has been confirmed.

Identify the phasing of the work. *(Please include the number of working days as well as the project start and end dates.)*

Signing for the applicant _____ Date 06/01/06

Printed name of signer R. T. Duncan

Cenotaph/Monument Restoration Program (CMRP)
Application Checklist

This checklist must be completed and included with all supporting documentation.

Do not write in the shaded space - For office use only	
Received by	
File Number	Date

☐	Funding application general form completed and signed by an authorized individual (Chairperson, Mayor, Executive Director, etc.).
☐	Written verification that applicant has authority to undertake the conservation work.
☑	Evidence of registration with National Inventory of Military Memorials or a copy of application form to this organization.
☑	A budget breakdown, including time frame for delivery of the final project.
☒	Drawings and specifications for the conservation work to be funded by this program.
☒	A copy of any condition assessment or investigation reports that have been produced, if available.
☒	Documentation related to an official heritage designation of Cenotaph/Monument.
☒	Copies of all contractors' estimates.

PLEASE SUPPLY THE FOLLOWING PHOTOGRAPHS OF THE CENOTAPH/MONUMENT IN ITS CURRENT CONDITION

☒	Quality close up photophaphs of the problem areas. *(The number of photographs should be sufficient to make the nature of the problem you wish to address clear to the reviewers.)*
☒	One overall shot showing the site and setting, and their relation to the cenotaph/monument.
☒	Photos of each side of the cenotaph/monument.

I AFFIRM THAT the information in this application is accurate and complete and the project proposal, including plans and budgets, are fairly presented. I agree that once funding is provided, any change to the project proposal will require prior approval of the Department. I agree to publicly acknowledge funding and assistance by the Department, in accordance with the terms of the funding agreement. I also agree to submit a final report, and where required, financial accounting for evaluation of the activity funded by the Department. I understand that the information provided in this application may be accessible under the *Access to Information Act*.

Applicant Authority		
Authorized signature	Printed name/title	Date
[signature]	ROBERT T DUNBAR	06/01/06

Shop : Atelier
405 Bertrand Street
Winnipeg, Man. R2H OP4

BRUNET Monuments. Third Generation

Charles Brunet
Phone (204) 233-7864
Fax (204) 233-3299

QUOTATION SHEET

NAME : Norwood Legion C/o Mr Rob Dunbar Date : June 15th 2016

Address : 134 Marion St

Postal Code :

Phone Number : 233-2329

NOTE :

All prices include: Monument, Base (grey granite), Lettering (Excluding future names & dates), design, setting in cemetery unless otherwise mentioned.

Cemetery : Coronation Park

To re-place 9pcs of Tyndall Stone and re-point base of Mnt.

To clean entire mnt. and Seal with proper Sealant.

Note: All cleaning to be grinding and preassure washing with acids No Sandblasting

Cost: $12000.00

350.00 PST on Material

840.00 GST on all

$13,190.00

Merci – Thank You

Per :

BRUNET MONUMENTS INC.