APPENDIX C – PROPERTY PHOTOS – WILLIAM WHYTE NEIGHBOURHOOD

These property photos reflect different ways in which vacant and derelict properties can manifest themselves as problem properties: as a vacant & boarded homes; as a vacant, boarded, and burned-out homes; as rubble piles; and as empty lots attracting illegal solid waste dumping. All properties are located in the William Whyte neighbourhood.



Located on Burrows Avenue. Spring 2025.



Located on Aberdeen Avenue. Spring 2025.



Located on Pritchard Avenue. Spring 2025.



Illegal dumping & solid waste on vacant lots. Spring/summer 2024.