

APPENDIX C – PROPERTY PHOTOS – WILLIAM WHYTE NEIGHBOURHOOD

These property photos reflect different ways in which vacant and derelict properties can manifest themselves as problem properties: as a vacant & boarded homes; as a vacant, boarded, and burned-out homes; as rubble piles; and as empty lots attracting illegal solid waste dumping. All properties are located in the William Whyte neighbourhood.



Located on Burrows Avenue. Spring 2025.



Located on Aberdeen Avenue. Spring 2025.



**Located on Pritchard Avenue.
Spring 2025.**



**Illegal dumping & solid waste on vacant lots.
Spring/summer 2024.**